

Acton

Phone: +16612331166
4519 Sierra Highway
Acton, California
Email: nsultana@tss786.com



2023 PJ Trailers 5 in Channel Buggy Hauler B5 YEAR LONG SALE

Type	Trailer or Truck Bed	Category	Car Hauler
Stock#	17320	VIN	3CV1C2325P2656620
Location	Acton	Year	2023
Status	Available	Condition	New
Manufacturer	PJ Trailers	Model	B5182-BW
Floor Width	83in / 6ft 11in		
Color	Black	MSRP	12999.99
Construction	Steel	Monthly Payment	194

<https://tss786.com/unit/2023-pj-trailers-5-in-channel-buggy-hauler-b5-year-long-sale-742483>

Price: \$9,600.00

MSRP: \$12,999.99

Monthly Payment: \$194.00

Description

AVAILABLE NOW !!! COME TO SEE IT IN PERSON AT OUR LOCATION 4519 SIERRA HWY ACTON ,CA 93510 JUST NORTH OF THE SAN FERNANDO VALLEY/ SANTA CLARITA VALLEY NEAR LOS ANGELES SPECIFICATIONS

2 5/16 Ball Bulldog Coupler
Safety Chains
1 Top Wind Drop-Leg Jack (7K)
2 Dexter E-Z lube Axles, Idler Brake
4 Leaf Double-eye Spring Suspension
4 15 White Spoke Wheels
4 -ST205/75R15 Radial Tires
Electric Breakaway Kit w/ Charger
Rubrail Stake Pockets
9 High Drive Over DP Steel Fenders
5 Channel Ramps w/ Holder
5 Channel Frame Tongue
3 Channel Crossmembers 24 on Center
Blackwood Pro Full Deck
102 Wide Deck
DOT Approved Flushmount LED Lights
All-Weather Wiring Harness (7-way RV)
Sand Blasted, Acid Washed, Powder Coated
82 1/2 Between the Fenders
5 year Dexter Axle Warranty
2 Dovetail w/ 5 Rear Slide-in Ramps
Mount Only for Spare Tire
Rear Trailer Support Jacks

16oc Crossmembers
Advertised pricing excludes applicable taxes title and licensing and dealer set up and are subject to change without notice. Pricing may exclude any added parts, accessories or installation unless otherwise noted. Sale prices include all applicable offers. Not all options listed available on pre-owned models. Contact dealer for details.

WARNING: Operating, servicing and maintaining a passenger vehicle, an off-highway motor vehicle or a recreational marine vessel can expose you to chemicals including engine exhaust, carbon monoxide, phthalates, and lead, which are known to the State of California to cause cancer and birth defects or other reproductive harm. To minimize exposure, avoid breathing exhaust, do not idle the engine except as necessary, service your vehicle or vessel in a well-ventilated area and wear gloves or wash your hands frequently when servicing your vehicle or vessel. For more information go to <https://www.p65warnings.ca.gov/products/passenger-vehicle> and <https://www.p65warnings.ca.gov/products/marine> .
