Northside Trailer Sales

Phone: +13177692460
11985 East State Rd
Zionsville, Indiana
Email: nsts969@aol.com



USED 1989 MqQuerry 5H Slant Horse Trailer

Type	Horse Trailer	**Category**	Horse Trailer
Stock#	75489	**Location**	Northside Trailer Sales
Year	1989	**Status**	Available
Condition	Used	**Manufacturer**	Other
Model	5H Slant	**Floor Length**	276in / 23ft
Floor Width	84in / 7ft	**GVWR**	14000
Payload Capacity	14000	**Axle Capacity**	7000
Color	White	**Pull Type**	Gooseneck
Axles	2	**Construction**	Aluminum
Stalls	5	**Shortwall Length**	4in / 0ft 4in
Configuration	Slant		

https://northsidetrailer.com/unit/used-1989-mqquerry-5h-slant-horse-trailer-816264

Price: $8,500.00

Description

USED 1989 McQUERRY 5H SLANT STEP UP HORSE TRAILER
Tandem 7000# Rubber Torsion Axles
ST235/85R16 LRE Radial Tires
16" 8 bolt Wheels w/Stainless Covers
Electric Brakes on All Wheels
Spare Tire Mounted Under GN Nose
Drop foot jack
14,000# GVWR
White with Gray Stripe
2-5/16" Adj. Height GN Coupler
6 Wire Plug
7' wide, 23'bed length, 7' inside height
Ceiling and all walls insulated & Lined with Mill Finished Aluminum
Aluminum Floor with Rubber Mats
DRESSING ROOM: 4' LONG SHORT WALL; Door on short wall
Carpeted floor, jack wall and GN nose
Roof and walls insulated and lined in mill finish aluminum
Sliding window in each side of GN and in door
One non-powered roof vent with broken handle
Two interior lights with switch above door
Six bridle hooks
STALL AREA
Unload ramp in front of first stall; Storm door with window
Rubber lined interior walls; Padded dividers (Rear divider pad is in DR)
Four drop down feed doors with windows, windows in butt wall
Three interior lights, Five 2-way roof vents
Two interior ties per stall; Eight exterior ties (3 on left side, 5 on right side)
Double rear doors; Double cam latches on solid rear post
REAR TACK: SOLID WALL, NOT REMOVABLE
5 saddle racks,12 bridle hooks, 2 brush trays on door, 1 Blanket bar on left wall
NOTE: Includes original straight coupler and 6" extended coupler.
Body of trailer is in better than average condition. Needs new tires, dated 2014.
** Note: Axle trolley is rusted through, needs replaced.
ALL USED TRAILERS SELL AS IS
